

Accomplishment Report of Repair and Maintenance of Physical Facilities for the Training Calendar Year 2020

- 1.** Repair and Maintenance of Housekeeping Pathway Roof Extension damaged by typhoon
- 2.** SSVTC Organic Farm
- 3.** Tile setting and Installation of Air conditioning unit of Relocated Assessment Office
- 4.** Repair and Replacement of Damaged Roof of Welding and Conference Hall
- 5.** Installation of Fire Extinguishers and Emergency Lamps at the Administration building, Male and Female dormitory and Power House
- 6.** Repainting of School Billboard and Update of School Directory
- 7.** Clearing of Fallen trees inclined to the EPAS building
- 8.** Repair of Roof of EPAS Building damaged by typhoon
- 9.** Replacement of Damaged glass of the aluminum door at Farm School
- 10.** Reinstallation of CCTV and upgrade for Additional CCTV cameras and TV Monitors for Assessment Center

1. Repair and Maintenance of Housekeeping Pathway Roof Extension damaged by typhoon



Housekeeping building with extended roof for pathway cover.





2. SSVTC Organic Farm



Main Entrance of Organic Farm



Plant Trellis and Hydroponics



Plots for Plants made of Nylon and Steel Frame



Canal with water supply for Tilapia Fish pond / Unserviceable cars were repainted with green and in secured with bamboo perimeter for cage of Organic Chicken Cage





Cage and passage way for organic chicken.



Frame for ornamental and vegetable plants



Station for Hydroponics planting facility



Hydroponics installed with steel frame, PVC pipes and water supply system


3. Tile setting and Installation of Air conditioning unit of Relocated Assessment Office



Installed Air Conditioning Unit at the Relocated Assessment Office



Tiles installed at the flooring of Assessment Office



Tiles installed at the flooring of Pantry of Assessment Office



Tiles installed at the flooring of Lobby of Assessment Office

4. Repair and Replacement of Damaged Roof of Welding and Conference Hall



Repaired Building Roof of Welding and Conference Hall



Repaired Building Roof of Welding Building



Repaired Building Roof of Welding and Conference Hall



Repaired Building Roof of Welding laboratory waste and segregation area

5. Installation of Fire Extinguishers and Emergency Lamps at the Administration building, Male and Female dormitory and Power House



Installed Fire Extinguisher at Power House



Installed Fire Extinguisher at Male Dormitory



Installed Fire Extinguisher at Female Dormitory



Installed Emergency Lamp at Male Dormitory



Installed Emergency Lamp at Female Dormitory

6. Repainting of School Billboard and Update of School Directory





7. Clearing of Fallen trees inclined to the EPAS building





Fallen trees that caused damaged to EPAS Building





8. Repair of Roof of EPAS Building damaged by typhoon




Repaired Building roof of EPAS



Repaired Building roof of EPAS



9. Replacement of Damaged glass of the aluminum door at Farm School



10. Reinstallation and Upgrade for Additional CCTV cameras to the Assessment Center and Installation of 2 units TV Monitors for Relocated Assessment Office



Installed DVR and TV Monitors for CCTV system of the Assessment Center

